KONECRANES[®]



01/2024







Introduction

Customers with a maintenance agreement and/or TRUCONNECT® Remote Monitoring have access to yourKONECRANES.com, our cloud-based customer portal.

Usage data, maintenance data and asset details are linked, giving a transparent view of events and activities over any selected time interval. Aggregated data can be viewed, analyzed and shared quickly, for a single asset or an entire fleet. Insights can be drawn by observing anomalies, patterns and trends, helping users make informed maintenance decisions.



Anomalies can show up as faults, such as overloads. These events are considered abnormal and should be addressed promptly as they occur. Knowing when an overload occurs is the first step in identifying its cause.



Patterns help reveal relationships between variables. For example, recurring alerts such as overheats indicate where changes in equipment or process may be desirable.



The study of **trends** can help prioritize corrective action and investments. Analyzing data behavior over time makes predictive maintenance increasingly feasible.



Data security

Konecranes digital services have been awarded ISO/IEC 27001:2013 certification for information security management. The ISO/IEC 27001 certificate demonstrates a commitment to proactively manage the information security of Konecranes digital services and ensure compliance with legal and customer requirements. The certification applies to the development and delivery of the yourKONECRANES.com customer portal, CheckApp for Daily Inspections and the Slings and Accessories Inspection app and the TRUCONNECT suite of remote service products.

Your service data – streamlined

yourKONECRANES streamlines data access by organizing large volumes of information—including inspection and maintenance findings, TRUCONNECT data and alerts, asset lists and service spend—into easy-to-read graphs and charts in a single location.

You can see fault history and prioritized assets according to chosen criteria for a quick view of pain points for a single asset or across their entire fleet.

The portal also offers data archiving and retrieval options, including document uploads and electronic reports suitable for printing. In addition, yourKONECRANES provides a possibility for you to receive automated e-mail notifications of available reports.

yourKONECRANES.com guide 2



Overview

The **Overview** page shows open items including open safety risks, production risks and TRUCONNECT statuses that require immediate attention.

If a risk has been identified for a component and a repair has not been completed, then the fault is considered open.

The Service Calendar and Reports section shows the number of service visits, assets serviced and total findings on those assets in the selected time frame.

The Overview also includes a quick view of quotations including those that need approval or that have expired.



Assets

The **Assets** page gives you a **fleet view** that can be filtered, for example, by location, asset criticality and asset type. From the Asset Reports button multiple different reports options can be generated into an Excel file, such as Open risks, Service history, Material History and Service spend.

Each Asset card shows the general asset identifiers, and how many open items relate to the asset. To find out more, click the asset card to see more details on the Asset summary view. From the summary card click the View Asset to see all your asset details and information.

≡ | Asset Fleet

< Back

Activity type

Service Requests

Findings and Actions Safety Risks Undetermined Condition

Service Product

MAINMAN Assessment

OSHA Periodic Compliance

Service history by
v
Component

Ouotations

Filter Clear filte

YOURKONECRANES

Crane 5 Single girder Single girder EOT - 1 trolley chain hoist



Here you can generate the asset report. You can for example select Open risks, Service history, Material History and Service spend.

×

12

🗎 Jun 27, 2023

🗎 Jan 11, 2022

🛱 Jan 11, 2022

🛱 Jan 14, 2020

🗎 Jan 14, 2020

Service Agreements

The Service Agreement section contains the agreement info and the agreement service plan.

In the Agreement Information and Summary sections you can see the details of your agreement with Konecranes. Contact information, service products and assets under agreement are included here.

In the **Assets and Service Plan** you can easily check the past and upcoming services for each asset per year.

The number indicates

performed on the asset

each month. Expand to

how many service

activities will be

see the details.

Assets and Service Plan ^ Service Status 2022 88% 0% 1% 10% Open Service Completed In Progress Delayed Service Plan < 2022 > Expand All Oct Asset lan Feb Ma Anr May lun hul Aug Ser Nov Dec Crane 5 Single girder Single girder EOT - 1 trolley chain hoist 2 1 ^ Load Test 1 MAINMAN Assessment Oil analysis 1 1 1 OSHA Frequent Compliance Inspection 1 OSHA Periodic Compliance Inspection 1 Routine Maintenance Crane 1 Double girder Double girder EOT - 1 trolley chain hoist 2 2 з 1 ~ Crane 2 Double girder Double girder EOT - 1 trolley chain hoist 2 з 1 2 1 ~ 2 Crane 3 Single girder 3 1 1 ~ Single girder EOT - 1 trolley chain hois Crane 4 Single girder 2 1 з 1 Single girder EOT - 1 trolley chain hois 2 1 Crane 7 Pillar Jib crane 2 1 ~ Pillar jib crane - electric wire rope hoist Crane 6 Light crane system 2 1 1 2 1 ~ Light crane system - double girder

of criteria.

You can change the year here.



Quotations

Quotation details

including contact info.

A pdf of the quote can

be downloaded.

This page shows open, accepted, declined and expired quotations, which are uploaded to the portal by Konecranes representatives for your consideration.

< Back



Service Calendar and Reports

The **Service Calendar and Reports** page shows you service activities in a calendar view. A color-code logic shows the status of the service and filtering allows you to see activities by asset criticality, service product and task type. Clicking on a month will allow you to see a detailed list of service activities.

Colors indicate status: green includes all completed, approved and closed service requests; yellow is in progress; grey is planned in the future; and red is an open service request where the planned date is five days or more past due.



Service Request

Filter by any number of criteria.

After a service visit, we perform a Service Review to go through open recommendations and quotes, answer questions and plan next steps. There are several ways to see this information on the portal – you can find your Service Request information from the main menu as well as the Overview page by clicking Service Calendar and Reports.

This information on the Service Request page will be discussed during your Service Review to help explain findings, to review open quotations and recommend and plan next steps.

Customer and service information

The details of the service visit including service products, technician name, contact information and dates are listed in this section.

Summary

This section highlights the findings and actions from the service visit. Safety risks, production risks, undetermined conditions, improvement opportunities, repaired items and if available – quotes and declined items – are listed. A graph shows findings and actions by asset and the details of those findings are listed below. Quotes for needed work can be attached here and downloaded.

Service Request Over bulkere (service) YOURKONECRANES Note: Service Request 1-68252680804-D Cations and Service Information Summary Envice Request 1-68252680804-D Cations and Service Information Summary Envice Request 1-68252680804-D Cations and Service Information Summary Envice Request 16000 Summary Envice Request 16000 Summary Envice Request 16000 Summary Envice Request 16000 Summary Summary of fin Summary of Summary Summary o							-	
CURCINCECACLESS			0 Q	S Demo Customer, Location 1				E Service Request
ter en benefits en benefits e	share the	Download or s	2022 O Down	Generate Report				OURKONECRANES
Determined outside in a service information increase and servi	rt by email	Service Report	Servic	Ī		t 1-68252680804-D	Service Request	
<pre>mpoint structure ^</pre>				4 ,	~	Information	Customer and Service	er Selection
						montation		ponent structure
torus metalow text services Regent State: Completed Services Regent State: Completed Services Regent State: Completed Services Services Regent State: Completed Services Regent State: Completed Services Re					^		Summary	findings and actions
<pre>perce congenent structure inge and Actions inge and Actions Up determined Conditions inge and Actions Up determined Conditions (Later nere Attemments (2) <u>Not</u> <u>Action Up determined Conditions (Later nere</u> Attemments (2) <u>Not</u> <u>Actions Up determined Conditions (Later nere)</u> <u>Attemments (2) <u>Not</u> <u>Actions (2) Attemments Actions (2) Attemments <u>Actions (2)</u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></u></pre>						Completed	Service Request Status:	t component structure
<pre>ing and Actions '</pre>						MAINMAN Planned Maintenance	Service Products:	blete component structure
Fidding and Actions Production Real With I production Real With I production Real I as Setty Reals I as Setty Reals <td< td=""><td></td><td></td><td></td><td></td><td></td><td>16</td><td>Assets Serviced:</td><td>ings and Actions</td></td<>						16	Assets Serviced:	ings and Actions
<pre>including agreed and Koncernate including agreed and Konc</pre>	information	View service in	View s				Findings and Actions	
tais based tais b	eement typ	including agree	includi					ety Risks Production Risks
<pre>www.memory locations in the contraction of the data because in the contraction of the data because the contraction of the data because in the contraction of the data because the data because the contraction and data because in the contraction of the data because the data because the data because the data because in the data because the data because</pre>	ies contact	and Konecrane	and Ko			7 Quotes	15 Safety Risks	able to Complete
<pre>minit leverable minit lev</pre>								provement Opportunities
summers: les							7 Production Risks	nment Acceptable
<pre>ins in the the temperson of the tem</pre>						ondition	7 Undetermined Co	asurements
I of victuality							Not able to Complete	tes ^
v Work Packages By v t criticality t critic						portunities	9 Improvement Opp	9
t criticality Moderate Low be Product t Name t Name t Name t Constitution of certain components on serviced/inspected cranes cannot be directly verified through visual inspector without further diasembly and/or the use of other inspector instructed removes and/or porting of this account in the scope of this scope o							-	v Work Packages By
Moderation Iowing ice Product MANN Planned Maintenance it Name it Name it abels Moderation Moderation it Name it Name it abels Moderation Moderation it it is a product <	findings	Summary of fi	Sumn			et (Top 5)	Findings and Actions by Asse	t Criticality
<pre>idee Product ^ MMN Hanned Maintenance idee Product ^ MMN Hanned Maintenance it Name</pre>	for the	and actions fo	and a	•				Moderate I ow
ice Product ^ MAN Planned Maintenance t Name _ Labeis	ervice	completed ser	comp		5	2	Crane 7	
MANA Planned Maintenance At Name Labels	asv-to-read	request in eas	reque			4	Crane 6	rice Product
at Name Labels Ourse 3 Ourse 3 Netel The condition of certain components on serviced/inspected cranes cannot be directly wrified through visual inspection without further disassembly and/or the use of othre inspection methods. These advanced services are excludeed from these opt othre service. Inspection without further disassembly and/or these or othreacemendations and/or governing regulations. These components are listed separately and identified as follows: Undetermined Conditions (Unable to Inspect - Not in Scope) Image: Conditions (16 Assets) Atdachments (2) Findings and Actions (16 Assets)	format	color-coded fo	color-			3	1	IMAN Planned Maintenance
Netel The condition of certain components on serviced/inspected cranes cannot be directly wellfied through visual inspection without further diassembly and/or the use of other inspection methods. These advanced services are excluded from the scope of this service. Inspect of these components should follows: Undetermined Conditions (Unable to Inspect - Not in Scope)	onnaci		COIOI				Crane 4 1	et Name
Labels Core 8 Image: Core 8 <td< td=""><td></td><td></td><td></td><td></td><td></td><td>3</td><td>Crane 2</td><td></td></td<>						3	Crane 2	
Note! The condition of certain components on serviced/inspected cranes cannot be directly wrified through Visual Inspection without further disassembly and/or the use of other inspection methods. These advanced services are excluded from the scope of this service. Inspect of these components should follow Defereormmendations and/or governing regulations. These components are listed separately and identified as follows: Undetermined Conditions (Unable to Inspect - Not in Scope)						4	Crane 8	Labels
Note! The condition of certain components on serviced/inspected cranes cannot be directly werlifed through visual inspection without further disassembly and/or the use of other inspection methods. These advanced services are excluded for governing regulations. These components are listed separately and identified as follows: Undetermined Conditions (Unable to Inspect - Not in Scope) Image: Conditions (Unable to Inspect - Not in Scope) Attachments (2) Add <								
Undetermined Conditions (Unable to Inspect - Not in Scope)					ctly verified through visual se advanced services are excluded OEM recommendations and/or	amponents on serviced/inspected cranes cannot be directly verified sembly and/or the use of other inspection methods. These advance specials frequency for these components should follow OEM recom mponents are listed separately and identified as follows:	Note! The condition of certain co inspection without further disass from the scope of this service. In governing regulations. These cor	
Wiew Descriptions / Learn more Add v Add/view attack Attachments (2) Add v Add/view attack Findings and Actions (16 Assets) v Add/view attack						tions (Unable to Inspect - Not in Scope)	Undetermined Conditi	
Attachments (2) Add Add/view attack Findings and Actions (16 Assets)			_			() View Descriptions / Learn more		
Findings and Actions (16 Assets)	achments.	Add/view attac	Add/v	◀	Add 🗸		Attachments (2)	
					~	16 Assets)	Findings and Actions (1	
Undetermined Conditions: Unable to Inspect - Not in Scope (16 Assets)					6 Assets) 🗸	ons: Unable to Inspect - Not in Scope (16 Assets	Undetermined Conditio	

Service Request

Asset details

The assets in the service request are listed in this section. The findings for each asset are listed along with the details such as fault code, risk and a recommendation. You will also find comments from the inspector or technician.

Findings are prioritized with safety and production risks listed first. You can also filter by findings and actions as well as asset criticality, service product and task type.

							Clicking on the asset name w show you all activities for tha asset in the selected timefrar
■ Service Request YOURKONECRANES				🚱 D	emo Customer, Location 1 enerate Report	• Q 2022 •	Yeu oop alee oop
Filter	Findings and Action	s (16 Assets) C Learn more	^				short component structure or complete
Clear Selection Component structure	Crane 7 Single girder Et	DT - 2 trolleys wire rope hoists	~				by clicking here.
Short component structure Complete component structure	Only findings and ac	tions Short component structure	Complete component structure	⊲			
Findings and Actions ^ Safety Risks Production Risks	Aug 23, 2020	! Rope guide Worn	Expand All	4			- Click the arrow to
Not able to Complete Improvement Opportunities Comment Acceptable		Latch Damaged	Quote 🗸				related to the finding.
Measurements Quotes ^		Worn Poperation control	♀ Quote ♀		! Rope guide	-	
Quote Show Work Packages By 🎽		Contacts worn I Operation control Contacts worn	Quote 🗸		Worn Tasks: Date Reported:	Visual assessme Aug 24, 2020	ent, Lubricate, Operational assessment
Asset Criticality ^		Markings Other fault Travelling gear	~		Technician: Component Path: Task Type:	Mike Hoist Trolley 1B / Hois Visual assessme	ting machinery 1B East / Rope guide ent
MAINMAN Planned Maintenance		Improper mounting Hoisting brake - holding Comment: Measure holsting brake, 13.95mm - ok	` `		Fault Code: Risk: Recommendation:	Worn Safety Risk Replace	
Own Labels ~		Acceptable Hoisting brake - holding Comment: Measure hoisting brake. 13.95mm - ok Acceptable	~		Comment:	rope guide worm	recommend replacing
	Jan 14, 2018	Condition monitoring unit / 1B Measurements	~				
		Condition monitoring unit / 2A Measurements	~				
		Mie	He				
		Jan 14, 2018 Mike H	oist, Technician / NT0000				

Service Request

Undetermined Conditions

The Service Request page in the portal will list individual components that have an Undetermined Condition and are not in the scope of your agreement.

An Undetermined Condition indicates that the component condition could not be directly verified through visual inspection without further disassembly and/or the use of other inspection methods.

These advanced services are generally excluded from the scope of typical compliance and preventive maintenance inspections. Consultation Services may be added to a service program or offered on a stand-alone basis to assess the condition of these components.

You may also see components listed as Undetermined Condition - Not able to Complete. This indicates that the component condition could not be directly verified through visual inspection as a result of asset configuration and/or obstruction. In this case, the visual inspection was part of the service scope, but it was not completed.



Documents and reports

The **Documents** page shows documents that have been added during the selected time frame. These include inspection reports and manually uploaded files. Files can be downloaded, and you can also add your own documents. Only legally required documents are automatically available. All online reports are available in the Service Review section.

	$\equiv \mid$ Documents		🚱 Demo Customer, Location 1 👔 Q
Filter by	YOURKONECRANES		(Š 2020 9
document type.	Filter Clear Selection By Type ^ Uploaded Labels ^ hook Hook MAINMAN Service Reports Mainman Planned Reports Mainman Planned Reports_Short Oil Analysis Oil Analysis test	19 Location Documents Online reports and documents available for completed services Service Review Image: Colspan="2">Image: Colspan="2" Image: Colspan=	You can find your Service Reports in the corresponding Service Request found in the Service Review section.
	Photos Service Review Reports Service Reports Test pendant	Test October 9, 2019 8:00 PM Edit Test_H.txt michael.crane@konecranes.com Test Michael.crane@konecranes.com KC-AF_Example.pdf Oil Analysis Oil Analysis	
		Serivice Review Report April 27, 2017 11:23 AM Edit SERVICE_REVIEW_REPORT_1-33309947322.pdf michael.crane@konecranes.com Serivice Review Report April 27, 2017 11:23 AM Edit	
		SERVICE_REVIEW_REPORT_1-33309947322.pdf michael.orane@konecranes.com Service Review Reports Click to download the document.	

CheckApp for Daily Inspections

Daily Inspection

The crane or hoist is not locked out for service

My personal protective equipment is as

I know the location of crane main isolation

witch and I have free access to it at all times

All signs, labels, and warnings are properly in

The crane shows no loose, damaged, jammed,

or missing parts or oil leaks. No part is in

ntact with open power sources

nstructed for this site and task.

ancel

and the hook is empty.

il spots, or other

place and readable

ng area.

This page shows information from CheckApp for Daily Inspections. Prior to each new work shift or each new lift (depending on applicable regulation), a daily inspection should be performed. Konecranes CheckApp for Daily Inspections provides an electronic logbook for performing and recording daily inspections.

The daily inspection is a visual and functional test / check to identify deficiencies. Any observed deficiency represents a potential safety risk. The daily inspection is performed by crane operator or other equally competent customer personnel. Performing daily

inspections does not reduce or replace need to perform Frequent or Periodic inspections by Konecranes service professionals.

The daily inspection view is available only for those assets with Konecranes CheckApp for Daily Inspections. A fleet view for assets with CheckApp over a selected time frame is available in the Business Review section. See page 23 for more information.



User Management

Customer managers that have CheckApp for Daily Inspections for their assets can create or delete CheckApp access for operators who perform Daily Inspections.

Each CheckApp user must identify themselves using their CheckApp credentials.



Slings and Accessories

This page shows information from the **Slings and** Accessories Inspection. This inspection has been designed to inspect non-maintainable load lifting attachments and accessories that are attached to the crane hook during operation. The inspection identifies deficiencies and deviations from local statutory safety and health regulations.

The inspection service utilizes radio frequency identification (RFID) tags to help quickly and reliably identify attachments and a smartphone app to record load lifting attachment inspection data. The information on the portal helps you keep track of inventory, execute audits and plan for replacements.

The fleet view shows all recorded loose lifting devices for the selected location. By default, the devices in this list are sorted after the next due inspection.

Devices that are not inspected yet or are past due should be taken out of service without delay and should be inspected as soon as possible to avoid a safety risk.

Filter by an	y number of criteria. = Slings and Acces YOURKONECRANES	ssories Inspection	Get a report sent a your email address report is only a su is not compliant w requirements. Clic download a compl	as a link to s. Note: thi mmary and ith statutor k on a devi iant report.	s I 'y ce to	😵 s	elect cust	omer 🧯	Q 8	Swit Dev Insp	tch bei vice De pectior	tween tails and Details.	J					
	Selected location(s) Search Location(s)	Slings and Accessori	es Inspection				ß	Generate Re	eport									
	Customer Location 1, Austin Street 1, Austin, Texas, USA	Customer 39 Devices					Device	Details	✓									
	Customer Location 2 Street 2, Montgomery, Alabama,	Device Type	Specification	Inventory No.	Serial No.	WLL	Length	Manufact	turer									
1	USA Customer Location 3 Street 3. Detroit Michigan, USA	Textile Eyesling	With suspension			300lb	3.00ft								ШE	The insp	ection	
e	Customer	Wire rope Sling	With hook	N123	123456	1000lb	30.00ft	-		i	From t info vie	nis devic ew vou c	e an			nistory s nspectio	nows a ons wh	ich
es ty	Street 4, Albany, New York, USA Customer Location 5 Street 5, Los Angeles, California,	Load Securing Lashing Chain		001zurr	00119012021	1250lb	1.00ft	Pewag		F	print o compli	r downlo ant indiv	ad a idual			our inspe nave per	ectors formed	d
	USA Customer Location 6	Textile Round sling		-		-				i	inspec	tion repo	rt.			on this d	levice.	
	Harbour street 1, Miami, Florida, USA	PSE / Fall Protection Safety Harness		-	12345s	50lb	2.00ft	•	$\equiv \mid$ Slings and A	Accessorie	es Inspectio	on				¢	Demo Custom	er 🚯 Q
,	Status ^ Passed (Not Repaired)	Textile Web sling	Protective hose	23	667664	4lb	2.00ft	Pewag	YOURKONECRAN	IES								9
a tion	Passed (Repaired)	Textile Round sling suspension gear	EB-7/8	-	6510	2lb	1.20ft	YOKE	< Back	D	evice info				►	Print PDF		
cute	Not checked Failed (Not Repairable)	Textile Round sling suspension gear	With eye hook (latch)	-	5510	2lb	1.20ft	YOKE		Si Si	iling - Chair ling, With hoo Building A - Hal	Alloy						
	Failed (Repairable)	Textile Round sling		-		2000lb	1.00ft	Demag		P	roperties	-				dit Properties		
es bio	Out of Service	Chain Sling	With connecting link, With grab hook, With master link, With safety hook	Kcd0001	051120202015	2900lb		Customer		Di Ty Ty	evice Type ype Specificati ype Specificati	on 1 on 2	Slir Slir Wit	ng - Chain Alloy ng th hook				
.1115	Device Type Manufacturer	Textile Round slind suspension dear	With connecting link			65lb	Devie tag i	ce deta nformat	ils and		ength /ork load limit o. of Legs erial No.		200 2 12:	00lb 34567				
	Functional Location	Chain	With connecting link	2345	123456789	2500lb	1.00ft	Pewag		in M Ye	iventory No. Ianufacturer ear of Constru	tion	12 AB 19	345 C Co. 95				
bluc	Building A, Bay 1	Textile Bound sling	Protective hose			3lb	2.00ft			Fu	unctional local ag informat	ion	Bui	ilding A - Hall 2				
sk.	Building A, Bay 7	Textile	With connecting link			300lb	30.00ft			Ta Ta	ag type ag UID		Phy 45	vsical ID Tag 6767				
	Building B, Bay 2 Building B, Bay 3	Textile Round sling	Single layer	6655	44556	6lb	55.00ft	Artex		ln s	nspection H	liStOry Inspection Type	Interval	Inspected by	Date			
	Service Requests V	Chain					2.00ft		A	1	Passed Date of Next In	Visual and functional spection: Jan 11, 20:	12 months	Michael Crane	Jan 12, 202	1	◀	
								-		1	Passed	visual and functional	12 months	Michael Crane	Nov 30, 202	10 🗸		
		Click de info vie	evice name to open															4.5

TRUCONNECT Remote Monitoring collects condition, usage and operating data from control systems and sensors on an asset and provides alerts of certain anomalies.

Analyzing and identifying anomalies, patterns and trends in TRUCONNECT data helps you make informed maintenance decisions and prioritize actions.

Collected data varies depending on asset make and model but typically covers condition and expected service life of critical components, running time, lifted loads, motor starts, work cycles and emergency stops. Additional TRUCONNECT options allow certain assets to be equipped with hoisting brake and/or inverter monitoring.

		Solution Demo Customer Location 1 (i) Q
Crane 5 Single girder Single girder EOT - 1 trolley chain	Open Items All Activities TRUCONNECT® Documents Asset Info	() 2022 (9
Preset Time Range Start Date	End Date	
Current Month V Select Date	Select Date Clear Time Range	

TRUCONNECT®	
Condition	Expand All
Hoist DWP	~
Crab thrust rockers Service Life	~
Brake Service Life	~
Contactors Service Life	~
Learn more about Condition	

Operating Statistics Expand All Operation Hours ~ Load ~ Events and Alerts ~

E Learn more about Operating Statistics

Ψ.

TRUCONNECT page for an asset **Summary**

The Summary section contains the main items that require attention in each category.

The shortest current service life of a component is retrieved from the Condition Monitoring section. Those values will change over time due to differences in the wear rate of components and different crane operating patterns, as these can significantly accelerate the wear rate. The effects of operation are described more closely in the Operating Statistics section.

The cumulative number of alerts in the review period is retrieved from the Alert section. Details are provided in the Pareto analysis of the alerts.

From the Operating Statistics section, the current most significant problem that could affect the safe operation or condition of the crane is added to the summary.



Condition section

Condition monitoring shows the current condition of the components, any risks related to safety and production, and the estimated remaining service life based on the usage history. Condition monitoring can also be used to check the component replacement frequency, which provides a clear indication of upcoming maintenance needs and how changes in the operator's actions affect the service life of components.

This information can be used to plan and schedule preventive maintenance in order to improve safety and reduce unplanned downtime.



Hoist DWP is the calculation of the remaining service life of the hoist and an indication of the remaining fatigue life of the machinery components. When the DWP value approaches zero, the hoist should be overhauled or replaced. Portion shows the calculated remaining service lifetime of the brake. When the value approaches zero, the entire electromagnetic disc brake should be changed and the shoe brake or thrustor type disc brake inspected. Portion shows the calculated remaining service lifetime of hoist contactors – up/down direction, fast speed and brake contactors. When the value approaches zero, contactors should be changed. The service lifetime is directly influenced by the usage rate of the hoist and, most significantly, by the use of jogging/inching.

Alerts section

Overload

A hoist overload occurs when a lift over the rated capacity is made or attempted. The periodic graph shows the number of overloads. The cumulative graph is the running total to date.

Emergency stop

When using a pendant, an emergency stop will register if the operator engages the e-stop button while the hoist is in motion. An e-stop also registers when the hoist is in motion in the up or down direction and the power supply or control is interrupted, when the hoist is operated to the limit switch, or when the pendant battery is low.

The periodic graph in single asset view shows brake service lifetime in terms of the number of e-stops. The hoist brake wears down 50 times faster with emergency stops than with normal stops.

Motor over temperature

A hoist motor over temperature is recorded each time the hoist motor stops operating due to an over temperature condition. The periodic graph shows the number of over temperatures. The cumulative graph is the running total to date.



The Pareto analysis displays and ranks the most important causes of alerts related to the safety and usability of the crane.

These indicate a safety risk to the crane or its operation. Safety-critical risks can include emergency stops, overloading and brake faults.

4

^

Learn more

Alert trend Sep 2019 - Aug 2020

Jan Mar May

Nov

Emergency or abnormal stop in

hoisting motion

Production Critical Alerts

Production Critical Alerts

20

Daily Average 1.8

Production Critical Alerts during period

and control system faults.

Fault in multi-hoisting, requests for running not simultaneous 20 These indicate production risks that result in crane stoppage or production downtime. Production-critical risks can include motor overheating, inverter faults

Learn more

Alert trend Sep 2019 - Aug 2020

Mar May

Operating statistics

Operating statistics show how different crane operating patterns affect the safe operation and condition of the crane and the service life of critical components.

Operating patterns can significantly influence the service life and safety of individual components. This section also shows usage rate differences between different hoists and the subsequent differences in their remaining service life.

This section is designed to promote appropriate operation in order to achieve optimal results in terms of the safety, service life and maintenance costs of the crane investment.



Once a year, or as needed, we like to meet with you at a management level for an in-depth assessment of our service relationship – looking at progress, feedback and documented value. We'll discuss recommendations and plan jointly.

Service KPIs

This section shows the number of service visits, work packages, assets serviced, modernizations, retrofits and consultation services performed during the selected time period.

The Trends graph reveals faults found for work packages and assets serviced. You can view any combination of findings and actions in this graph.

Findings and Actions shows the number of safety risks, production risks, undetermined conditions, improvement opportunities and repaired items for the selected time period. Findings and actions are also shown for each asset in the agreement.



TRUCONNECT section

This view of your TRUCONNECT information shows the number of alerts and usage by running hours for the selected time period. An alerts summary shows the number of safety alerts in total and by asset. Usage by Running Hours shows the running hours of each asset as well as the number of starts.

The information in this section can help you pinpoint connected assets that need attention and make appropriate plans for budgeting and maintenance.



Show all (6)

yourKONECRANES.com guide 22

CheckApp for Daily Inspection

This view shows a summary of all daily inspections performed within the selected time frame. A list of inspected assets is shown with the number of passed and failed inspections per asset. This helps you identify assets that need attention and to focus on corrective actions.

Each checkpoint shows how that many times that checkpoint has passed or failed per asset. This helps you identify assets that have frequent issues with a particular checkpoint such as limit switches or hook latches.

			🚱 Demo Customer 🕕 🔍
	YOURKONECRANES		© 2022 9
	K Back	Inspection Summary Checklists	
	Filter Clear filter	Inspection Summary	
	Failed Passed	Demo Customer Location 1, Austin Demo Customer	
	Attachment Photo	< 2022 >	
Filter by pass, fail	Asset Crane 1 Double girder	Jan Feb Mar Anr May Jun	Easy to identify accets
or caution.	Crane 5 Single girder	Jul Aug Sept Asses 5/5 27 13 Pailed Passed	and/or practices that
	Crene 3 Single grider	Oct Nov Dec	need attention.
	Crane 4 Single girder		
		40 Activities	
		Nov 21, 2022 Mikel Ruiz de Austri Valdivielso 23.04	
		Daily inspection completed Crane 1 Double girder SMT (m: 20211125)	
		Nov 16, 2022 21:49 Daily inspection completed	
		Crane 5 Single girder DC-PR0 10-1000 1/1 H5 V6/1,5 (en: 20211129)	
		Nov 16, 2022 4.33 Aubert Ndikurtyo Daily inspection completed - 1 failed, 14 passed	
		Crane 1 Double girder SMT (sn: 20211125)	
Get a good view of ass	et or	4.32 Aubert Ndikuriyo Can't Ind	
safety procedure issue	s, and	Nev 16 2022	
records for auditing ne	to-date	3.30 Daily inspection completed	
records for additing he		SMT (sr. 2021125)	
		20.46 Ade Ardyanto Daliy inspection completed - 1 failed, 14 passed	
		crané 1 Double grider SMT (an: 20211125)	
		20.45 Ade Ardyanto Not proper to use in this area	
Get a good view of ass safety procedure issues complete, detailed, up- records for auditing ne	et or 5, and to-date eds.	4.32 Aubert Nsikunyo Can tind Nov 16, 2022 13.33 Benen Valkar Daly impection completed Carse 1 Occube groer SMT (sn 2021125) Nov 14, 2021 Ade Adylanto Daly impection completed - 1 failed, 14 passed Carse 1 Occube groer SMT (sn 2021125) 20.48 Ade Adylanto Daly impection completed - 1 failed, 14 passed Carse 1 Occube groer SMT (sn 2021125) 20.48 Ade Adylanto Not proper to use in this area	

Spend section

Your spend information is summed up in this view. You can look at agreement costs as well as costs not in your agreement. You can also filter by service products.

Trends by Service Type show the amount spent on different service products over a five-year period.

Total spend and spend by service type is highlighted in an easy-to-read chart and is also broken down by asset allowing you to see, for example, which assets experienced the highest number of on-call service visits.





konecranes.com